Beech Street (Route202) / Cherry Street (Route 202) / Northampton Street (Route 5)









- Bike Share rental station is located along southeast corner of the intersection. Bike lanes are located to the north of the intersection along Northampton Road (Route 5) however there are no bike provisions at the intersection or along other approaches.
- The signal head back plates are old and need new retroreflective stipes.
- Pedestrain signal heads are dated and do not provide countdown.
- All approaches do not have enough signal heads per lane
- Left turn yield on green warning sign is needed for Northampton Street (Route 5) southbound approach
- Pavement markings along several locations at this intersection were observed to be faded
- Northampton Street northbound approach has exclusive left turn lane but does not have a separate signal head or phase dedicated to left turning traffic
- The turn lanes and shared lanes are not marked by appropriate pavement markings

