

Riverdale Street (Route 5) / Morgan Road / Dagget Drive



- Aggressive driving, speeding, heavy congestion, and high volumes of commercial vehicle traffic with tight turning radii are some of the factors that could lead to higher probability of crashes along these intersections.
- Several sign posts along the medians seem damaged by collision with motor vehicles
- Dual left turn lanes from the Riverdale Shopping Plaza driveway into Riverdale Street (Route 5) do not have pavement markings through the intersection to guide the vehicles in proper lanes. This created increased possibility of sideswipe crashes
- Red Light running was observed along Riverdale Street (Route 5) northbound approach at the intersection with Morgan Road. Optically programming the two signals could help in addressing this aggressive driving and speeding problem.
- Right turning traffic from Riverdale Street (Route 5) southbound approach into Morgan Road gets backed up behind commercial vehicles entering Agrimark
- Dagget Drive intersection traffic gets backed up all the way to Morgan Road intersection and vice versa
- Lack of optical programming along signals

