

## Boston Road (Route 20) / Stony Hill Road



- Heavy congestion, long delays during peak hours, aggressive driving, following too closely, potential red light running, and weather conditions could be some of the factors contributing to higher crashes at this intersection.
- The low clearance underpass located to the north of the intersection along Stony Hill Road has narrow travel lanes
- The left turn lane along Boston Road (Route 20) eastbound approach is short and vehicles have to often cross double yellow center line because of tight turning radii
- Residents along Stony Hill Road get their driveways blocked by heavy traffic queues during peak hours
- The curb openings for the Big Y Express gas station are too close to the intersection
- Faded Pavement Markings