

Buckley Boulevard / Chicopee Street (Route 116) / Prospect Street / Yelle Street / Montgomery Street / North Chicopee Street



- Heavy Congestion, difficult geometry, restricted right of way, low height railroad underpass, old equipment, and lack of proper coordination between the signals could be some of the factors contributing to higher crashes at this location
- This location needs detailed study to examine proper improvement measures; short and long term. Any such proposed study needs to include all three intersections and advance warning signs along the roadways
- Require advance warning signs for low clearance railroad underpass along the all roadways
- Observed red light running from Prospect Street westbound right turn lane

